

FIELD INSPECTION REPORT

Date of Inspection: 3.12.20	District: Rohtas
Division: RWD Bihraungaj	Length (km): 1.67 Km.
Name of the Road: Dumaroun Distributory to Kharshadih Khurd	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10301002082
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing WBM in pots	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

[Signature]
3.12.20
J.C.

NAME: Rajeshwar Prasad Singh