

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Dharbhanga
Division : R.W.D (W) Dist - Benipur		Length (km): 1.00 km
Name of the Road: Milkis Hospital to Andauli village		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U (Pavement part) ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ (N.A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓ (N.A)
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N.A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N.A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: GITENDRA KUMAR

DESIGNATION: ASSISTANT ENGG.

(Signature)
02/12/2020
A. B. Prasad

(Signature)