FIELD INSPECTION REPORT

Date of I	nspection:	5/12/20	District: Quy ulari	,
Division: Backa			District: Bag usaw Length (km): 1.150	
Name of		11 (21 th 10 at a 21	10.10.00	clation inch.
Scheme/	Programme:	MAINTENANCE	ala to shebput Kamas	CATALON AND AND AND AND AND AND AND AND AND AN
Package	No.:	the design of the second secon	Road Id No.: 32010 60 8	The state of the s
Status of	f the Project:	Ongoing/Completed/	ompleted/Under Maintenance	
Work is	a case of:	The state of the s	gradation/ Maintenance	
Sl. No.		Parameters to b	e checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U/
b)	Condition of Surfacing			S/kJ
c)	Riding Quality			_8/U
d)	Road Camber			<i>√8/</i> U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U /*/i->
c)	Condition of railings/slab/approach for Bridges			S/SRI/U NUA

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

3.

a)

4.

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Road Furniture

Compliance History

Status of ATR's & any others

NAME: Rameshwas chaudhary
DESIGNATION: Executive Enginees

(Signature) live Engineer

Works Division, Balla

S/SRI/U NIA

Yes/No

MO