FIELD INSPECTION REPORT

Date of Inspection: 5/12/10			District: Jamui		
Division: Jemui			Length (km): 3.5 Km		
Name of	the Road: Si	candra Luchisara	i PWD roud To Khard	lih Tal Sakar	
Scheme/	Programme:	MAINTENANCE			
			load Id No.: 208041008	346	
		Ongoing/Completed/Un	V		
	a case of:	New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be	checked	Remarks	
4	Pavement			Large 40 Mars Conf	
a)	Road Junction condition			S/U ✓	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U ✓	
d)	Road Camber			√8/ U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
i i je je	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-S/SRI/U N	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	k ekamoji kate ekt	100.48 200		Company of the Compan	
a)	Status of ATR'	The state of the s		MA	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<i>O</i> .

Charles 10

Silvino

(SEXOCUTIVO REGINEET Jamus (SEXOCUTIVO PROJECTION JAMUS DIVISION, Divisi

missig Kth

NAME:

DESIGNATION: