

FIELD INSPECTION REPORT

Date of Inspection :	07/12/2020	District:	Aurangabad
Division :	Aurangabad	Length (km):	6.50 km
Name of the Road:	Risip to Simara Road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10602800835
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S	
b)	Condition of Surfacing	Ten points surface damage.	
c)	Riding Quality	S/U	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	
f)	Contraction Joints provided or not (CC Pavement)	S	
g)	Compaction of flank slope & raincuts if any	No.	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Sunil Kumar
3/12/2020
(Signature)

NAME: