

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020.	District :	MUNGER.
Division :	KHARAGPUR-TARAPUR.	Length (Km) :	3.600 K.M.
Name of the Road :	Bhumasi Se Shashengram via Bhusichak Khandwihari Kulehara road to Kharagpur-Tampur Road.		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	Proj 10-20008033
Status of the Project :	Ongoing/Completed/Under Maintenance		✓
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No	✓
4	Compliance History		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI) ✓	
Unsatisfactory (U)	

NAME: SUKESH KUMAR.
DESIGNATION: A.E

S. Kumar
04.12.2020.
(Signature)