

# FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: Lakhisarai	
Division : Lakhisarai		Length (km): 2.50 Km.	
Name of the Road: Bannu Bagicha to Gokri Halt via Korriyapur Halt			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Gross Drainage	✓ S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture	✓ Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History	NO	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S) ✓

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

04.12.2020

04/12/2020  
AE

(Signature)

NAME: