

FIELD INSPECTION REPORT

Date of Inspection : 2.12.20		District: Kaimur
Division : Sheikhpura		Length (km): 2.850 km
Name of the Road: Mandla to Bafra		
Scheme/Programme:	MAINTENANCE	Road Id No.:
Package No.:	Ongoing/Completed/Under Maintenance	
Status of the Project:	New Connectivity/Up gradation/ Maintenance	
Work is a case of:	Parameters to be checked	Remarks
Sl. No.		
1.	Pavement	✓S/U
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	✓S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	✓Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Birendra Kumar

DESIGNATION: F.E.

Birendra Kumar
2.12.20
(Signature)