FIELD INSPECTION REPORT

Date of l	Inspection: O	3/12/2	strict: Rothsten	
Division		110/20/20	noth (km): 1 amk	M
	the Road:		buther to chama	lampura 1
THE RESIDENCE OF THE PARTY OF T	Programme:	MAINTENANCE	10mg/NU/V	
			Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	Be 12		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance I	illion to the		
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

This road is forester to (RCD)

Food contraction Department Ani 12 2020

(Signature)

H'E

NAME:

AVINASH KUMAR

DESIGNATION: Assistant Englineez (A.E.)

Scanned with CamScanner

Scanned with CamScanner