## FIELD INSPECTION REPORT

(a late	4	영향들 10 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
Date of Inspection:	04/12/2020 .	District: Samastepuz	
Division: Samastipuz		Length (km): 3.00 km	
		to Rasalpur via Kewas Ma	rdir
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.: 32010100 852	5A
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to	be checked	Remarks
国际的特别经验。这个需要的现在形式和分配。		在国际的技术,被关键的对象处理也强制的关闭。 人名 "一个"	1 d. For. 1 .7

Sl. No.	Parameters to be checked	Remarks	
1.	Payement	Many set	
a)	Road Junction condition	<b>√</b> \$/U	
b)	Condition of Surfacing	SHU.	
c)	Riding Quality	\$/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g) -	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c) .	Condition of railings/slab/approach for Bridges		
3.	Rond Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		
-			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

04/12/20 20 (Signature)

NAME: Vivekananal