

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Rohas
Division : R.W.D.-Bikramganj	Length (km): 4.200 km
Name of the Road: Yedav more to mukundpur Dhoukhatra Pala Baghar via Karanj	
Scheme/Programme: MAINTENANCE	New maintenance policy 2018
Package No.:	Road Id No.: 10301/01023
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	up to W.B.M ✓ S/U
b)	Condition of Surfacing	Gr - III ✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	To be done Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m only sign board ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

02/12/2020
J.E.
(Signature)

NAME: Satish Kumar