

FIELD INSPECTION REPORT

Just started.

Date of Inspection :	3.12.20	District:	Roh t as
Division :	RWD Bikraungay	Length (km):	2.41 Km.
Name of the Road:	Bikraungay Damaraon to Narayapur Mahabir.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10301302009
Status of the Project:	☒ Ongoing ☐ Completed ☐ Under Maintenance		
Work is a case of:	☒ New Connectivity ☐ Up gradation ☐ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rajeshwar Prasad Singh

(Signature) 
3/12/20
I.E.