FIELD INSPECTION REPORT

Date of Inspection: 02 12 2020			District: Ausangebod	
Division: Dand nager Name of the Road: Rock Rouge Road Schools Proceedings			District: Ausangebog Length (km): 2.933 km	The state of the s
Name of t	the Road: Ro	L Gays Road	to Bajidpyx	-
Scheme/P	rogramme:	MAINTENANCE	e by willia's	
Package No.:			Road Id No.:	100
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		OF COLUMN AND AND AND AND AND AND AND AND AND AN	o be checked	Remarks
SI. No.	Payamont	Parameters	o be checked	Rema

Sl. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing	√S/U		
c)-	Riding Quality	-S/U		
d)	Road Camber	~S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U		
c)	c) Condition of railings/slab/approach for Bridges			
3.	Road Furniture	STATE		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

16		
	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
温泉	Unsatisfactory (U)	4.00

Hote week in Progress

(Signature)

NAME: Paevan kumer Rom