

# FIELD INSPECTION REPORT

<b>Date of Inspection :</b> 03.12.2020		<b>District:</b> MUZAFFARPUR
<b>Division :</b> MUZAFFARPUREAST-1		<b>Length (km):</b> 1.90
<b>Name of the Road:</b> NH 102 Bagrangpuram Road No. 1 to Bhagwanpur Prathmik vidyalaya		
<b>Scheme/Programme:</b> MAINTENANCE		yadnagar meherchak + basti via Tagon
<b>Package No.:</b>		<b>Road Id No.:</b> 32nd 102
<b>Status of the Project:</b>		Ongoing/Completed/Under Maintenance
<b>Work is a case of:</b>		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: KUNIL KUMAR

DESIGNATION: J.E

*Kunil Kumar*  
31/12/2020  
J.E

*[Signature]*  
3.12.20  
(Signature) E.E