

# FIELD INSPECTION REPORT

|                        |                                            |              |         |
|------------------------|--------------------------------------------|--------------|---------|
| Date of Inspection :   | 3.12.20                                    | District:    | Rohas   |
| Division :             | RWD Bikaner                                | Length (km): | 4.50 Km |
| Name of the Road:      | Bikaner Durgam Road Bikaner via Parbhani   |              |         |
| Scheme Programme:      | MAINTENANCE                                |              |         |
| Package No.:           |                                            | Road Id No.: |         |
| Status of the Project: | Ongoing Completed Under Maintenance        |              |         |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |         |

| Sl. No. | Parameters to be checked                                                                                        | Remarks     |
|---------|-----------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                        |             |
| a)      | Road Junction condition                                                                                         | S/U         |
| b)      | Condition of Surfacing                                                                                          | S/U         |
| c)      | Riding Quality                                                                                                  | S/U         |
| d)      | Road Camber                                                                                                     | S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No      |
| 2.      | Cross Drainage                                                                                                  |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U     |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U     |
| 3.      | Road Furniture                                                                                                  |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m Yes/No |
| 4.      | Compliance History                                                                                              |             |
| a)      | Status of ATR's & any others                                                                                    |             |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

(Signature)

3/12/20  
J.E.

NAME: Rajeshwar Prasad Singh