FIELD INSPECTION REPORT

Date of Inspection: 9-12/2020 Division: GOGRI			District: 1		
			Length (km): 1.9		
Vame of the	Road: (nulum Gross at	ed east Jamalph to Grorain	12 Bathan -Vis	Broken
Scheme/Prog		MAINTENANCE		Jola, Ku	rmi Tol
ackage No.:		10000	Road Id No.:		
A CONTRACTOR OF THE PROPERTY O			ed/Under Maintenance		
Commence of the last	ie ou	Company of the Compan	/Up gradation/ Maintenance		,
Sl. No.		Parameters (to be checked	Remarks	
I. Pav	rement				
a) Ros	Road Junction condition			. VS/U =	
b) Co	Condition of Surfacing			S/U	to the
c) Ric	Riding Quality			VS/U	
d) Ro	Road Camber			√\$/U	
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f) Co	Contraction Joints provided or not (CC Pavement)				
g) Co	Compaction of flank/slope & raincuts if any			Yes/Nov	
2. Gr	Gross Drainage				
a) Co	Condition of head walls in Hume pipe culverts including its painting			∪S/SRI/U	
b) Co	Condition of Abutment & Wing walls, Slab in RCC culverts			∽S/SRI/U	
c) Co	Condition of railings/slab/approach for Bridges			S/SRI/U	N. A
3. R	Road Furniture				
a) W	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Management of the first of the
4." C	Compliance History				

Overall Rating

a)

Satisfactor Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME:

Status of ATR's & any others

DESIGNATION:

J.12.7020 J.E Manej Ko. Sangaron Junion Engineer

(Signature)