FIELD INSPECTION REPORT

Date of Inspection:		04 . 12 . 2020	District :	Munat P.		
Division :	KHARAGP	UR- TARAPUR.	District :	MUNGE R.		
Name of the Road :		•	Length (Km):		2.250 KM.	
		Kharagfur- nuzaftorgenj PMGSY path me Rajganj se Ghoshfur Rote hue Teghra tak fath.				
		The that leghon	tak fath.			
Scheme/Pr	ogramme :	MAINTENANCE -				
Package No. :			Road Id No.: Project 1D - 2080 3800 844			
Status of the Project :		Ongoing/Completed/Undo	er Maintenance			
Work is a case of :		New Connectivity/Up gradation/Maintenance				
Sl. No.		Parameters to be che		Remarks		
1	Pavement					
a)	Road Junctio	n condition		S/U		
b)	Condition of Surfacing			S/U		
c)	Riding Quality			√S/U		
d)	Road Camber			VS/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U (N.A.	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U			
3	Road Furniture					
′ 1	Whether sign boards/informatory/cautionary board/Km &					
	200m stones/Pavement road markings are provided and			Yes/No		
	maintained					
	Compliance History Status of ATR's & any others			No.		
a)	Status of ATI	cs & any others		/×0		

Overall Rating:

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SUKESH KUMAR DESIGNATION: A.E.

(Signature)