FIELD INSPECTION REPORT

Date of	Inspection: OG	2.12.2020	District: Subaul		
Date of Inspection: 02 · 12 · 2020 Division: Supaul			District: Supaul Length (km): 2.400		
Name of the Road: Karnpur Rajantur P.W.D. to Dhonai Kat				0	
Scheme	Programme:	MAINTENANCE	LITTO DE DESTAL ROS	raya	
Package No.: Road Id No.: 21004-906			A\$ 2.2		
Status of the Project: Ongoing/Cor		Ongoing/Completed	led/Under Maintenance		
Work is a case of: New Connectivity/Up a			p gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Ves/No N·A·	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainag	ge			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			∽s/sri/u	
c)	Condition of railings/slab/approach for Bridges			S/SRI/ U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's	s & any others		Not Regain	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

02.12.2020

(Signature)

NAME: Ran Vijay Kumar DESIGNATION: A.E., R.W.D; Supaul

Scanned by CamScanner