FIELD INSPECTION REPORT

	spection: 05/12/2020 District; Nalanda, District; Nalanda, Length (km): 10.500	
ivision:		Dan nur.
	he Rond: NH82 to Kumhari River) Sazbadhi via Raha rogramme: MAINTENANCE	100
ackage l	12 121 N	
	the Project: Ongoing/Completed/Under Maintenance	
	rease of: New Connectivity/Up gradation/ Maintenance	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U C
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U _
e)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painti	ng S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	Lave en la version de la versi

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Road work in progress in Pm 454-II.

NAME: Mukesh Vadau

DESIGNATION: J.B.