FIELD INSPECTION REPORT

ate of In	spection: 05/12/202	District: Nalander	
ivision:		Length (km): 0.610 KM.	A .
	ho Ronal: Save-Noge	van Road To Royai Bighs.	
	rogramme: MAINTEN	IANCE BISY FOR.	
Package No.: Road Id No.:			
	the Project: Ongoing/C	Completed/Under Maintenance	-
Work is a	case of: New Conn	ectivity/Up gradation/ Maintenance	A Part of the Part
SI. No.	Parameters to be checked Remark		
1.	Payement		
a)	Road Junction condition	S/U (
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber		S/U
e)	Whether free from de aggregates in case of CC	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slo	Yes/No	
2	Cross Drainage		
a)	Condition of head walls	S/SRI/U	
b)	Condition of Abutment	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
_: 3 .:	Road Furniture		
a)	Whether sign boards/stones/Pavement road r	Yes/No	
4.	Compliance History	in the second	
a)	Status of ATR's & any	others	

Overall Rating

	A 19 AND 19
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1

This Road work in FDR 3054 Temprony Restoration No face Propletion of the year Maintonce.

(Signature) Trans

NAME: Mulesh Yadan

DESIGNATION: J.E

Scanned with CamScanner Scanned with CamScanner