

FIELD INSPECTION REPORT

| | |
|---|--|
| Date of Inspection : 03/12/20 | District: KAIMUR |
| Division : Mohania | Length (km): 0.880 km |
| Name of the Road: Durguth Kalkail Road to Timbura | |
| Scheme/Programme: | MAINTENANCE |
| Package No.: MRN/19-20 Mohania 27 | Road Id No.: |
| Status of the Project: | <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/> |

| Sl. No. | Parameters to be checked | Remarks |
|---------|---|-----------------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓S/U |
| b) | Condition of Surfacing | ✓S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | ✓S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No |

Overall Rating :

Ongoing.

| | |
|---|-----|
| Satisfactory (S) | 'S' |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: SATYENDRA PRASAD LAL

(Signature) Sunny
03/12/20
J. Ro