## FIELD INSPECTION REPORT

Date of Inspection: District: Nolanda.					
Division: Biharstanit.			Length (km): 8.9cm		
ame of	f the Road: Go	ibinore To Pe	Sour wa Ultarnama, Edemant	ur, Itaras	
cheme	Programme:	MAINTENAN	CU		
ackage			Road Id No.:		
	f the Project:	A STATE OF THE PARTY OF THE PAR	leted/Under Maintenance		
Sl. No.				Remarks	
1.	Pavement				
n)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
)	Contraction Joints provided or not (CC Pavement)			Yes/No	
	Compaction of flank/slope & raincuts if any			Yes/No	
11 7	Cross Drainag	ge			
1)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRL/U	
)	Condition of railings/slab/approach for Bridges			S/SRI/U	
2 5 .	Road Furniture				
)	Whether sign stones/Pavement	boards/informat nt road markings	ory/cautionary Board/km & 200m are provided and maintained	Yes/No	
[第一]	Compliance H	Istory		10000	
	Status of ATR'	s & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	•

Taken in New mointenance Policy - 2018

Ajeet kumar singl

DESIGNATION: 7-E