FIELD INSPECTION REPORT

Date of	Inspection : 0	13-12-2020 District: West cham	
Division		kativagant Length (km)	paran
	f the Road:	Bouichalcharda to 161	
	/Programme:	MAINTENANCE Chap To 19	-
Packag		Road Id No.: 3180 8200 9	100
	of the Project:	Ongoing/Completed/Under Maintenance	13+
	s a case of:	New Connectivity/Up gradation/ Maintenance	
SI. No.	Parameters to be checked		Remarks
1.	Payement		
a)	Road Junction	S	
b)	Condition of	5	
c)	Riding Qualit	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		S
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction	S	
21	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts —		-
c)	Condition of railings/slab/approach for Bridges —		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance I	listory	
a)	Status of ATR	's & any others	No

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: RAM HARAYAHSHAH

DESIGNATION:

A.E