	FI	ELD INSPECTION REP	<u>ORT</u>	
Date Of	offen			
Division	2.75			
Name o	of the Road:	Sedhan to Bels	School	
Scheme	e/Programme	MAINTENANCE		
Package	e No .: Rm / BH / PIR / 19	/ooil Road Id	No.: 10401601	026/2019-20
Status of the Project:		Ongoing/Completeted/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
SI No.	I	Parameters to be checked		Remarks
1	Pavment		l_	
a)	Road Junction condition	on		S/U
b)	Condition of Surfacing	3		S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defin case of CC Paveme	ects such as visible cracks, exp	posed aggregates	Yes/No
f)	Contraction Joints pro	ovided or not (CC Pavement)		Yes/No
g)	Compaction of flank/s	slope & raincuts if any		Yes/No
2	Cross Drainage	4		
a)	Condition of head wa	alls in Hume pipe culverts inclu	uding its painting	S/SRI/U
b)	Condition of Abutme	nt & Wing walls, Slab in RCC	culverts	S/SRI/U
c)	Condition of railings/	slab/approach for Bridges		S/SRI/U
3	Road Furniture	·		
a)	1	informatory/cautionary Board markings are provided and m		Yes/No
4	Compliance History	· ·		
a)	Status of ATR's & ar	ny others		

Overall Rating	:	Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	

Unsatisfactory (U)
Mork Las ben Started for

Name: Ashok kumm

(Signature)

Desigination