FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020			District: Go palganj-		
Division: RWD (Hopalgany-2 Name of the Road: Dumaniya to T Scheme/Programme			Length (km): 3.00 km		
Scheme	Programme:	masiya to	Tandaspur		
Packag	e No.:	MAINTENANCE	•		
Status o	of the Project:	0	Road Id No.:		
Work		Ungoing/Completes	Ongoing/Gompleted/Under Maintenance		
SI. No.	A COMP & COLUMN	Thew Connectivity/	Jp gradation/ Maintenance	Remarks	
		Parameters to be checked			
1.	Payement			A COLUMN TO THE PARTY OF THE PA	
a)	Road Junction condition			Š/U	
b)	Condition of Surfacing			\$/U	
c)	Riding Quality				
d)	Road Camber			S/U	
				S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			NIA	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage			Yes/No	
where the same and					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			S/SRI/U	
AZZIA	et at the sub-line is in	A LAS COLOR POR SERVICE	and the same of th		
C	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	listory	9011		
a)	Status of ATR's & any others			UTT Light Co. Days	
				MO	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	581
Unsatisfactory (U)	

OSA2200 (Signature)

NAME: Subhash Chandra Verma

DESIGNATION: JE