

FIELD INSPECTION REPORT

Date of Inspection :	District: SARAN
Division :	Length (km): 5.60 km
Name of the Road: Vaidapur to Jalalpur Path under 3051 (MR)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31306500825
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U H.A
b)	Condition of Surfacing	S/U H.A
c)	Riding Quality	S/U H.A
d)	Road Camber	S/U H.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H.A
g)	Compaction of flank/slope & raincuts if any	Yes/No H.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U H.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U H.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	HO

Overall Rating :

Satisfactory (S)	SA
Satisfactory but requires Improvement (SRI)	SR
Unsatisfactory (U)	

work is ongoing

Amit K Chaudhary

NAME: 5/12/20

DESIGNATION:

SE

(Signature)