

FIELD INSPECTION REPORT

Date of Inspection :	09/12/2020	District:	Saran
Division :	Marhaura	Length (km):	8.550 Km
Name of the Road:	Lakhanpur to bagdiha via Pipra singhi Path		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	3/306500830
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>information board</i>
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	<i>✓ SRI</i>
Unsatisfactory (U)	

work is ongoing so all above point cannot be stated adjactly at Present

09/12/2020
(Signature)

NAME: ASHUTOSH KUMAR RANJAN

DESIGNATION: ASSISTANT ENGINEER