

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: BHOJPUR
Division : JAGDISHPUR	Length (km): 7.00 km.
Name of the Road: SH-12 Gashani to NH-30 Harigaon via Madura Sahangi Subenpur Road (Part-2)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10401708055
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & (raincuts if any) NO	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained ^{✓Yes} ^{✓Yes} _{✓S}	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature
03/12/2020
(Signature)

NAME: MANISH KUMAR, J. E