


FIELD INSPECTION REPORT

Date of Inspection :	08/12/2020	District:	BHOJPUR
Division :	JAGDISHPUR	Length (km):	4.00 km.
Name of the Road:	NH-30 Deulhingarj to Knsirath Railway station.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10401708059
Status of the Project:	Ongoing/Completed /Under Maintenance✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & (raincuts if any) NO	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


08/12/2020
(Signature)

NAME: MANISH KUMAR, J.E.