

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Bhojpur
Division : PIR	Length (km): 0.500
Name of the Road: Construction of Road from Nagri Takurbari via the House of Charpat Chaurasiya	
Scheme/Programme: MAINTENANCE	
Package No.: RM/24/PIR/19/0001	Road Id No.: 10401805003
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	(N/A) Yes/No
f)	Contraction Joints provided or not (CC Pavement)	(N/A) Yes/No
g)	Compaction of flank/slope & raincuts if any	(N/A) Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - (N/A)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N/A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Anil Kumar Prishra

deg- A/E