| | | FIELD INSPECTION RE | PORT | |
|-------------------------|--|---|---------------------------------------|--|
| Date O | f Inspection 03.12.2020 District -Blo | | ojbur | |
| Divisio | n Pivo Length (km): | | 1-250KM | |
| Name | of the Road: | Khaira Village to | Karwashin | the second secon |
| Schem | e/Programme | MAINTENANCE | | |
| Packag | ge No.: | Road Id | l No.: | |
| Status of the Project : | | Ongøing/Completeted/Under | Ongøtng/Completeted/Under Maintenance | |
| Work is a case of: | | New Connectivity/Up gradation/Maintenance | | <u></u> |
| SI No. | | | Parameters to be checked | |
| 1 | Pavment | | 1000 | Remarks |
| a) | Road Junction cond | ition | 7 | S/U |
| b) | | Condition of Surfacing | | S/U |
| c) | Riding Quality | | | |
| d) | Road Camber | | | S/U |
| | | | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | | Yes/No | |
| f) | Contraction Joints p | traction Joints provided or not (CC Pavement) | | Yes/No |
| g) | Compaction of flank | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2 | Cross Drainage | | | |
| a) | Condition of head v | valls in Hume pipe culverts inclu | ding its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | S/SRI/U | |
| 3 | Road Furniture | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | Yes/No | |
| 4 | Compliance Histor | у | | |
| a) | Status of ATR's & a | ny others | | |
| | 1 | | | |

| Overall Rating : | Satisfactory (S) | |
|------------------|---|--|
| | Satisfactory but requires Improvement (SRI) | |
| | Unsatisfactory (U) | |

Name: Roja Om Raxash Designation Executive Engineer

(Signature) (3)1212020