FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020		**District:**	BUXAR
Division : Dumraon		**Length (km):**	9.800 KM
Name of the Road: Ariaon Brahmsthan to Bagen Path.			
Scheme/Programme:	MAINTENANCE Maintenance Policy.		
Package No.:		**Road Id No.:**	
Status of the Project:	Ongoing/Completed/Under Maintenance		Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance

Sl. No.	Parameters to be checked	Remarks	
1.	**Pavement**		
a)	Road Junction condition	✓ S/U S	
b)	Condition of Surfacing	✓ S/U S	
c)	Riding Quality	✓ S/U S	
d)	Road Camber	✓ S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	yes
2.	**Cross Drainage**		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	**Road Furniture**		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	NO
4.	**Compliance History**		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

04/12/2020
JE

4/12/2020
AE

(Signature)

NAME: