## FIELD INSPECTION REPORT

7-12-20	District: Cray a
A STATE OF THE PARTY OF THE PAR	Length (km): 0.680
MAINTENANC	B
	Road Id No.:
Ongoing/Completed/Under Maintenance	
New Connectivity/Up gradation/ Maintenance	
	Ongoing/Compl

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	∕s/U
d)	Road Camber	∕S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ~
2.	Cross Drainage	<b>美國發展</b>
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	and the same of
a)	Status of ATR's & any others	NU

Overall Rating

Satisfactory (S)	Same
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

ALLI A-12-70 (Signature)

NAME: AKCIJESH 1 KUMZ Mulet DESIGNATION: A-E