

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020 District: Patna
 Division : Paligarh Length (km):
 Name of the Road: NH 93 to Khurd Road
 Scheme/Programme: MAINTENANCE
 Package No.: MR-N/19-20 Paligarh/04 Road Id No.:
 Status of the Project: ☒ Opening Completed/Under Maintenance
 Work is a case of: ☐ New Connectivity/Up gradation/ ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U
c)	Condition of railings/slab/approach for Bridges	S SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Note - work in progress

Supa
03/12/2020
J.C.

8.5 km.
03/12/2020
A.E.

03/12/2020
(Signature)

NAME:

DESIGNATION: