

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nagbada
Division :	Nagbada	Length (km):	
Name of the Road:	NH-82 (Kerjha) to NH-31 Kharat		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/HW/04	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m <u>Yes/No</u>
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Remarks: - Road transfer to RCD

(Signature)

J.E.

NAME: