

# FIELD INSPECTION REPORT

|                                                               |                      |
|---------------------------------------------------------------|----------------------|
| Date of Inspection: 02/12/2020                                | District: Amangabad  |
| Division: Daudnagar                                           | Length (km): 2.33 km |
| Name of the Road: Gokhale Road to Bagidpur                    |                      |
| Scheme Programme: MAINTENANCE                                 |                      |
| Package No.:                                                  | Road Id No.:         |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                      |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | Pavement                                                                                                             |          |
| a)      | Road Junction condition                                                                                              | S/U      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U    |
| c)      | Riding Quality                                                                                                       | ✓ S/U    |
| d)      | Road Camber                                                                                                          | ✓ S/U    |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No   |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No   |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No   |
| 2.      | Cross Drainage                                                                                                       |          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U  |
| 3.      | Road Furniture                                                                                                       |          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No |
| 4.      | Compliance History                                                                                                   |          |
| a)      | Status of ATR's & any others                                                                                         |          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

Work in Progress

*Pawan Kumar Ram*  
02/12/2020  
(Signature)

NAME: Pawan Kumar Ram

DESIGNATION: J.E.