

Work is in progress

# FIELD INSPECTION REPORT

| Date of Inspection : 03/12/2020                               |                                                                                                                 | District: - Aurangabad |        |
|---------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------|--------|
| Division : - Aurangabad                                       |                                                                                                                 | Length (km): 1.49 km   |        |
| Name of the Road: Aurangabad Nabinagar to Sonbarsa Khasra     |                                                                                                                 |                        |        |
| Scheme/Programme: MAINTENANCE NR 3054 New Maint. Policy-2018  |                                                                                                                 |                        |        |
| Package No.: NR-N/19-20 NRAB/33                               |                                                                                                                 | Road Id No.:           |        |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                                                                                                                 |                        |        |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                                                                                                                 |                        |        |
| Sl. No.                                                       | Parameters to be checked                                                                                        | Remarks                |        |
| 1.                                                            | Pavement                                                                                                        |                        |        |
| a)                                                            | Road Junction condition                                                                                         | S/U                    |        |
| b)                                                            | Condition of Surfacing                                                                                          | ✓<br>S/U               |        |
| c)                                                            | Riding Quality                                                                                                  | ✓<br>S/U               |        |
| d)                                                            | Road Camber                                                                                                     | ✓<br>S/U               |        |
| e)                                                            | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No                 | N.A    |
| f)                                                            | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No                 | N.A    |
| g)                                                            | Compaction of flank/slope & raincuts if any                                                                     | Yes/No                 |        |
| 2.                                                            | Cross Drainage                                                                                                  |                        |        |
| a)                                                            | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U                |        |
| b)                                                            | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U                |        |
| c)                                                            | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U                |        |
| 3.                                                            | Road Furniture                                                                                                  |                        |        |
| a)                                                            | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m                   | Yes/No |
| 4.                                                            | Compliance History                                                                                              |                        |        |
| a)                                                            | Status of ATR's & any others                                                                                    |                        |        |

Overall Rating :

|                                             |             |  |
|---------------------------------------------|-------------|--|
| Satisfactory (S)                            | in progress |  |
| Satisfactory but requires Improvement (SRI) |             |  |
| Unsatisfactory (U)                          |             |  |

*[Signature]*  
21/12/20  
(Signature)

NAME: Dinesh Prasad Singh