

FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District:	Aurangabad
Division :	Damohar	Length (km):	4.60 Km
Name of the Road:	Rafiqpur - Shivgarh Rd. to Bhatara - Bhatara		
Scheme/Programme:	MAINTENANCE (New Maintenance Policy-2018)		
Package No.:	N.A.	Road Id No.:	-
Status of the Project:	Ongoing/Completed/Under Maintenance (Ongoing)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- Above mention Road under new maintenance policy. Work just allotted to contractor for maintenance the Road under New Maintenance policy. Work not started at the direction given to contractor for work start early.

Asingh
(Signature) 2/12/20

NAME: Anurender Singh

DESIGNATION: - Junior Engineer