

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020 District: Aurangabad
 Division : Aurangabad Length (km): 5.50 km
 Name of the Road: Amba Teewa Biche Road to choraha path
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 62 MBO/20/19-20
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & cutouts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Work in Progress — N/A

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Sunil Kumar
 3/12/2020
 (Signature)

NAME: