

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020

District: Aurangabad

Division : Aurangabad

Length (km): 1.30 km

Name of the Road: Risiup Maharajgaon to Bhargavdha

Scheme/Programme: MAINTENANCE

Package No.: MR-N/19-20 Aurangabad/20

Road Id No.: 86 MRD/20/19-20

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	work in progress S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & inlets if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of A/R : & any others	

work in progress - N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

4/12/2020
(Signature)

NAME: