FIELD INSPECTION REPORT

Date of Inspection: 3-12-2020			District: Aurangalow	1.	
Division: Daudmager			Length (km): 4.200		
vame (f the Road: Do	20 hora-Salery	District: Auremgabore Length (km): 4.200 DWY Jou tour foreok un	dual ma	
	C	MAINTENANCE) a gross	
Packag		1	Road Id No.:		
			ed/Under Maintenance		
		CALAMADA PARAMANA	Up gradation/ Maintenance		
Sl. No		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
e)	Riding Quality			S/U	
d)	Road Camber			SIU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement) Yes/No				
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its paintin		S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance Hi	story			
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note-Work in Progress. B.M. work is in Progress,

<u>Tham!</u>
3-12-2026
(Signature)

NAME: Nomelon sharing

DESIGNATION: 5 E