

FIELD INSPECTION REPORT


Date of Inspection : 04-12-2020 District: Arwal
 Division : Arwal Length (km): 0.97 km
 Name of the Road: Baidhahad to Belkhar road to Nisarghar Saur
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance ongoing
 Work is a case of: ☐ New Connectivity ☐ Up gradation ☐ Maintenance

Sl No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SI
b)	Condition of Surfacing	SI
c)	Riding Quality	SU
d)	Road Camber	SI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contractum Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRII
b)	Condition of Abutment & Wing walls, Slab or RCC culverts	S SRII
c)	Condition of railings/slab approach for Bridges	S SRII
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

WOT/C
Just
Started

Overall Rating : work just started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 04/12/2020
 (Signature)

NAME: Indrajeet Ram
 J.E.