

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Arwal
Division : Arwal	Length (km): 6.30 km
Name of the Road: Buxhabad to Belkhar road to Haryana	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10603002031
Status of the Project: Ongoing Completed Under Maintenance	ongoing
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SA
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No
f)	Contraction Joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank/slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRIU
c)	Condition of railings/slab/approach for Bridges	SSRIU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of ATR's & any others	


Work
Just
started

Overall Rating : WORK JUST STARTED

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


09/12/2020
(Signature)

NAME: Indrajit Ram
J.E, Arwal