

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: Arwal
Division : Arwal	Length (km): 1.450 K.M.
Name of the Road: Makhumbur Harnakhash Path to Darheta	
Scheme/Programme: MAINTENANCE	3054 M/A (New..m. p) 10603002065
Package No.:	Road Id No.: Complete 1.45 K.M.
Status of the Project: ☒ Ongoing ☒ Completed ☒ Under Maintenance	Complete 1.45 K.M. under maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance up gradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	-
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sudama Yadav
02/12/2020
J.E.
(Signature) Kurtha

NAME: *Sudama yadav*