

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: ARWAL
Division : ARWAL	Length (km): 0.930 km
Name of the Road: Bhadasi Pakharapur Road to Dariyapur	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10603102006
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

work in progress

Overall Rating :

Satisfactory (S) work just started
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

03/12/2020
(Signature)

NAME: Praveen Kumar
AE (Kargi)