

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020 District: Arwal
 Division : Arwal Length (km): 1.690 km But work done 1.40 km.
 Name of the Road: Takiya H.S. to Sedpur
 Scheme/Programme: MAINTENANCE 3054 M/A (New m. p.)
 Package No.: Road Id No.: 10603102021
 Status of the Project: Ongoing/Completed Under Maintenance ☒
 Work is a case of: New Connectivity/Up gradation/ Maintenance ☒ Complete 1.40 km (under maintenance)
 up graded

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	—
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

NAME:

Sudama Yadav

(Signature)

Sudama Yadav
02/12/2020
J.E.
Karthi