

FIELD INSPECTION REPORT

Date of Inspection :	District: Amnol
Division : Amnol	Length (km): 2.73 K.M
Name of the Road: Kinger Kurtha road to Korkun	
Scheme/Programme: MAINTENANCE	1060310204
Package No.:	Road Id No.: NEW Maintenance
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	ongoing
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

WORK JUST STARTED

WORK IN PROGRESS (WORK JUST STARTED)

Overall Rating :

- Satisfactory (S)
- Satisfactory but requires Improvement (SRI)
- Unsatisfactory (U)

Prabhat
3-12-20
A.E
(Signature)

NAME: **PRABHAT KUMARRAJ A.E**
(KURTHA)