

FIELD INSPECTION REPORT

Date of Inspection : 4/12/2020	District: APURAL
Division : APURAL	Length (km): 20.500 KM
Name of the Road: Repair at Road from Karpi to Kurtha via Surajpur Sonbhadra	
Scheme/Programme: MAINTENANCE	Shadipur - Pondli Baha.
Package No.:	Road Id No.: 10603108004
Status of the Project:	Ongoing/Completed/Under Maintenance (under maintenance)
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No / partially
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No-ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Karan Patel Sharma - JE
Section - Karpi

(Signature) 4/12/20