

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date: 04-12-2020	District: Bhagalpur	
Bhagalpur	Length (Km): 5.850 km.	
The Road: Jagdishpur to Chandpur via Bada Tagerpur Road.		
Scheme / Programme: MAINTENANCE		
Package No.: Group No. 13	Road Id No.: 20703204006.	
Status of the Project: Ongoing / Completed / Under Maintenance		
Work is a case of: New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No NO
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating: Work has not been started yet.		
	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	—

NAME: Radho Ramas Sify
DESIGNATION: Assistant Engineer.

04/12/20
JF.

(Signature)

04/12/20
AE