

FIELD INSPECTION REPORT

Inspection: 4/12/20	District: Bhagalpur
Location: Bhagalpur	Length (Km): 1.4
Name of the Road: Fulwaria Shah Kund To Bhulani path	
Scheme / Programme: MAINTENANCE	
Package No.: group-1c	Road Id No.: 20703208107
Status of the Project: Ongoing / Completed / Under Maintenance C.S. process	
Work is a case of: New Connectivity / Up gradation / Maintenance	

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Cmpaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating: A.A given & This road is in under tender process.		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME:

Radha Raman Singh

DESIGNATION:

A-E

(Signature)

[Signature]
05/11/20
DE